

Feed Throats

NEW!!!

REBUILT!!!

REPAIRED!!!

Call us to discuss the lower cost, reduced maintenance feed throat design recommendations available to you only through Glycon.

912 Industrial Drive
Tecumseh, MI 49286
Phone: 800-255-9969
Fax: 517-423-7470



Feed Throat repair services and manufactured components include:

- Re-lining your current feed throat housing with grooved or smooth bore one piece constructed industry standard carbide liner .
- Re-designing your current, feed throat housing to accommodate Glycon's 2-piece welded liner assembly. The Glycon design does not rely on an "interference fit" between the liner and housing to contain cooling fluids. Unlike the 1-piece design, once you have the Glycon liner, the 2-piece design is self supporting and allows the customer to press out a worn Glycon design liner and install a new or refurbished liner .
- Exploring the possibility of going from a grooved feed design to a smooth bore feed throat, in combination with Glycon's DM2 high performance feedscrew, to approach grooved feed extrusion rates while eliminating accelerated wear issues inherent to grooved feed systems .
- Providing a low cost domestic source for feed throat maintenance to fit most plastic processing machinery .

